



# Quickstart Guide Boost Sensor



## Provided accessoires

- Sensor
- 3-way plug
- 5 pins for crimping

## Further information

For more information regarding your display or our other products please head to:



[www.canchecked.de](http://www.canchecked.de)



MAP sensor  
**absolute** ratings:  
0V = -31.1 kpa  
5V = 777.7 kpa

0V = -0.31 bar  
5V = 7.77 bar

0V = -4.51 psi  
5V = 112.8 psi



PLUG	3	2	1
A	5V	OUT	GND

For further questions or information visit our website ([www.canchecked.de](http://www.canchecked.de)) or get in contact with us via email ([info@canchecked.de](mailto:info@canchecked.de)).